| Ref # | Hits | Search Query | DBs | Default Operator | Plurals | Time Stamp |
|----------|------|--|---|---------------------|---------|------------------|
| L1 | 0 | @ad<"20011220" and all adj flash adj PC | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:29 |
| L2 | 0 | @ad<"20011220" and flash adj only near computer | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:29 |
| L3 | . 0 | @ad<"20011220" and flash adj memory near only near computer | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:29 |
| L4 | 3 | @ad<"20011220" and flash adj memory near based near computer | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:32 |
| L5 | 0 | @ad<"20011220" and firmware adj update near peripheral adj card | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:33 |
| L6 | 2 | @ad<"20011220" and firmware adj update and peripheral adj card | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:34 |
| L7 | 0 | @ad<"20011220" and firmware adj update near peripheral and assembly adj line | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:34 |
| L8 | 0 | @ad<"20011220" and firmware adj update near peripheral and assembly | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:34 |
| L9 | 1 | @ad<"20011220" and firmware adj update near peripheral | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:35 |

| L10 | 1 | @ad<"20011220" and firmware adj update near peripheral and wireless | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:37 |
|-----|----|---|---|------|-----|------------------|
| L11 | 0 | @ad<"20011220" and firmware adj update same PCI adj card and wireless | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:37 |
| L12 | 0 | @ad<"20011220" and firmware adj update same PCI adj card | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:37 |
| L13 | 0 | @ad<"20011220" and firmware adj update same peripheral near card | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:37 |
| L14 | 0 | @ad<"20011220" and firmware adj update same PCI near card | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:37 |
| L15 | 7 | @ad<"20011220" and firmware adj update and PCI near card | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:38 |
| L16 | 3 | @ad<"20011220" and firmware adj update and PCI near card and wireless | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:38 |
| S1 | 2 | "6687496".pn. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR . | OFF | 2006/01/02 09:41 |
| S2 | 2 | "5819054".pn. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/05 12:57 |
| S3 | 44 | "43742" and JP | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/05 12:58 |

| S4 | 16 | "43742" and JP and japanese | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/05 13:00 |
|-----|----|--|---|----|-----|------------------|
| S5 | 2 | "4636942".pn. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/05 13:01 |
| S6 | 2 | "4636946".pn. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/05 13:02 |
| S7 | 6 | JP-B-61-43742 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/05 13:06 |
| S8 | 3 | 61-43742 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/07/05 13:06 |
| S9 | 0 | @ad<"20011220" and wireless near fireware near update | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 13:49 |
| S10 | 0 | @ad<"20011220" and wireless near firmware near update | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 13:49 |
| S11 | 16 | @ad<"20011220" and wireless near firmware | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:01 |
| S13 | 0 | @ad<"20011220" and programmable near wireless near chip | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:02 |
| S14 | 0 | @ad<"20011220" and program\$5 near wireless near chip | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:02 |

| S15 | 561 | @ad<"20011220" and program\$5 same wireless same chip | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:02 |
|-----|------|---|---|----|-----|------------------|
| S16 | 3 | @ad<"20011220" and program\$5 same wireless near chip | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:02 |
| S17 | 1305 | @ad<"20011220" and firmware near up\$6 | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:55 |
| S18 | 272 | S17 and wireless | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:03 |
| S19 | 1 | S18 and wireless near firmware | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:06 |
| S20 | 17 | ("2003012091" "5,974,312" "6, 414,871" "6,449.476" "6,603,394" "6,715,067" "6,229,737" "6,687, 496").pn. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:08 |
| S21 | 497 | 713/1,2,100.ccls. and wireless | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:08 |
| S22 | 278 | S21 and @ad<"20011220" | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:08 |
| S23 | 12 | S22 and automotive | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:11 |
| S24 | 4 | S22 and wireless.ti. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:09 |

| | r | | r | | | |
|-----|-----|--|---|----|-----|------------------|
| S25 | 1 | S22 and assembly adj line | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:11 |
| S26 | 37 | @ad<"20011220" and firmware near up\$6 and car | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:56 |
| S27 | 0 | @ad<"20011220" and firmware near up\$6 and car and assembly adj line | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:55 |
| S28 | 0 | @ad<"20011220" and firmware near up\$6 near car | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:55 |
| S29 | 31 | @ad<"20011220" and firmware near up\$6 and automobile | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:56 |
| S31 | 0 | S26 and firmware.ti. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2005/12/31 14:56 |
| S32 | 0 | vehicle adj firmware.ti. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 09:41 |
| S33 | . 0 | vehicle near firmware.ti. | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 09:42 |
| S34 | 80 | vehicle near firmware | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 09:43 |
| S35 | 0 | vehicle near firmware near update | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 09:42 |

| S36 | 26 | assembly adj line and electronic near program | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 09:44 |
|-----|----|--|---|----|-----|------------------|
| S37 | 55 | assembly adj line and electronic near program\$5 and (car vehicle automo\$5) | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 09:44 |
| S38 | 7 | S37 and flash | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 09:45 |
| S39 | 26 | S37 and ROM | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 09:44 |
| S40 | 32 | S37 and @aD<"20011220" | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 10:10 |
| S41 | 17 | S40 and ROM | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 09:45 |
| S42 | 12 | @ad<"20011220" and integrated near BIOS and hard adj drive | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 10:10 |
| S43 | 0 | @ad<"20011220" and integrated near BIOS near hard adj drive | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 10:11 |
| S44 | 1 | @ad<"20011220" and integrated near BIOS near memory | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 10:14 |
| S45 | 1 | @ad<"20011220" and integrated same BIOS same flash adj disk | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 11:28 |

| S46 | 0 | @ad<"20011220" and PCB same BIOS same flash adj disk | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 10:14 |
|-----|---|---|---|----|-----|------------------|
| S47 | 0 | @ad<"20011220" and PCB same BIOS same flash adj drive | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 10:14 |
| S48 | 4 | @ad<"20011220" and BIOS same flash adj drive | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 10:24 |
| S49 | 2 | @ad<"20011220" and firmware same flash adj drive | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 10:25 |
| S50 | 0 | @ad<"20011220" and firmware same flash adj drive same board | US-PGPUB; USPAT; EPO; JPO; DERWENT; IBM_TDB | OR | OFF | 2006/01/02 10:25 |